



INSTALLATION STEPS

1. Cut a 85 mm(3 3/8") diameter panel hole(# II).You will need a minimum clearance of 85 mm(3 3/8") behind the panel to fit the gauge(# III).
2. Place the gauge body (# III) in the panel hole(# II),and then fasten it with fastening ring(# I).
3. Insert wire harness into port, and connect the ventilation hose with the bronze fitting of speedometer. Please make sure the connection is tight.
4. According to wiring instruction to do wire connection. Gauge can be connected to 12VDC and 24VDC power directly.
5. Select either red or yellow backlight by your fondness.